

Current Software Revision Level

*Note: For additional questions, please use the online **Request Support** form.*

Instrument	Current Software Revision Level
HFA II (Model 720 – 750)	Revision 14.2.1 Software / Revision 15.0.1 Software (Optional)
HFA II - i (Model 720i – 750i)	Revision 4.2.1 Software
FDT	Revision 3.01 Software
Matrix	Revision V6.02.03 Software
PreView PHP	Revision 1.4.3 Software
HARK 597 – 599	Revision B8 Software
ACUITUS (All Models)	Revision A14.2 Software
Lens Analyzer 350 / 360	Revision A3 Software
Lens Analyzer 370 / 380	Revision A5 Software
Corneal Topographer (ATLAS) 910 – 990	Revision A10.1 Software
Corneal Topographer (ATLAS) 991 – 995	Revision A12.2 Software - Download
Corneal Topographer (ATLAS) 9000	Revision 1.0
IOLMaster 1/2 (Windows 95)	Revision 3.01 Software
IOLMaster 3 (Windows 98)	Revision 3.02 Software
IOLMaster 4 (Windows XP)	Revision 4.08 Software / 5.02 (Optional)
HUB - 820	Revision H1 Software
OCT 2 (Model 2010)	Revision A3SA (Standard Analysis) or A3 (GAP) Software
Stratus OCT / OCT3 (Model 3000)	Revision 5.0(x)* Software <i>Note: *(x) revision number will vary depending on the instrument hardware configuration.</i>
Stratus OCT Review Software	Revision 5.01
Visante AC-OCT	Revision 2.0
Cirrus HD-OCT / 4000	Revision 3.0
GDxVcc	Revision VCC 6.0.0 Software
GDx ACCESS	Revision VCC 5.5.1.5 Software
GDx LEGACY	Revision 3.0.00 Software (Windows 98) / 1.0.16 (Windows 3.11)
TopSS-CL	Revision 1.0.10 Software (Windows 3.11)
ICG/ANGIO	Revision 3.0.23 Software (Windows 3.11)
Topps XL	Revision 3.0.13 Software (Window 3.11) Revision 4.0.06 Software (Windows 98)

Current Software Revision Level

*Note: For additional questions, please use the online **Request Support** form.*

Instrument	Current Software Revision Level
VISULAS YAG II	Revision 3.2 Software
VISULAS YAG II+	Revision 4.0 Software
VISULAS YAG III	Revision 1.02.48 Software
VISULAS 532	Revision 1.53 Software
VISULAS 532s PDT	Revision 2.00 Software Revision 2.6 Software (older systems) Revision 2.9 Software (new systems) <i>Note: Systems with software revisions less than 2.6 can only be upgraded to revision 2.6.</i>
VISUCAM Lite	Win 98 Models – Revision 2.1 / Win XP Models Revision 2.5
VISUCAM NM/FA	Revision 4.1 Software
VISUCAM PRO NM	Revision 4.1 Software
VISUPAC	Revision 4.3 Software (Depending on Hardware)